



PROJECT EXAMPLE

University of the West of Scotland

Following a recent storm our long-standing client UWS suffered some severe storm damage to a high-level flat roof on campus. Large sections of the flat roof were blown off and landed in the carpark area.

Once safe to do, our emergency team attended site to make safe.

The damage to the existing roof was beyond repair and full replacement was required. We worked closely with manufacturer IKO to conduct site survey and proposed a full new tapered built up felt system- Ultra Gold.

Our complete scope of works for this project consisted of,

- ▶ Emergency site make safe and clearance.
- ▶ Erection of scaffolding.
- ▶ Replacement of damaged brick around perimeter of roof structure.
- ▶ Replacement of uPVC roofline and rainwater goods.
- ▶ New IKO tapered Ultra Gold flat roof system.

New roof system comes with **IKO backed 20 years warranty.**